

C23: Silver Plated Copper Corrosion (Red Plague) Effective Date: 11/14/2019

Suppliers should take all steps necessary to prevent and detect the formation of corrosion (Red Plague) on wires per SAE ARP6400. This shall be flowed down to all sub-tier suppliers as applicable.

Deliverable:

Conductor not containing silver plated copper corrosion.